




Schemat statyczny



Przęsło 1 szt.1




Przęsło 2 szt.5




Pozycja 1.2


Przęsło 3 szt.1




Przęsło 4 szt.1




A-A




B-B



C-C



D-D



Poz. 1.2

Wykaz stali zbrojeniowej

| Nr pręta | Ø  | Długość | licz. w elem. | licz. w elem. | AO    | A-III |
|----------|----|---------|---------------|---------------|-------|-------|
|          | mm | m       | szk.          | szk.          |       |       |
| 1        | 18 | 547     | 3             | 1             | 1841  | 8     |
| 2        | 18 | 382     | 3             | 1             | 1146  | 3     |
| 3        | 8  | 120     | 27            | 6             | 3240  | 6     |
| 4        | 18 | 394     | 6             | 6             | 14184 | 6     |
| 5        | 18 | 379     | 3             | 3             | 5685  | 3     |
| 6        | 18 | 364     | 3             | 3             | 5460  | 3     |
| 7        | 18 | 514     | 3             | 1             | 13200 | 1542  |
| 8        | 18 | 352     | 3             | 1             | 1095  | 1095  |
| 9        | 3  | 8       | 120           | 23            | 2760  | 30714 |
| 10       | 3  | 8       | 120           | 23            | 2760  | 1986  |
| 11       | 3  | 8       | 120           | 23            | 14963 | 61354 |
| 12       | 3  | 8       | 120           | 23            | 70316 | 70316 |